

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One quarter corner common to Sections 9 and 16, T3N, R6W, W.M., Tillamook County, Oregon.

ORIGINAL

Post, now missing, from which a:

48" Fir bears N44°E 27 lks.; now 48" stump, scribes $\frac{1}{4}$ " S visible, lower face unexposed.

12" Hemlock bears S84 $\frac{1}{2}$ °W 13 $\frac{1}{2}$ lks.; now 18" stump, scribes $\frac{1}{4}$ " remaining.

RESTORED

Set 1 $\frac{1}{2}$ " x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY $\frac{1}{4}$ " S9 S16 1955 RE2311," 33 inches in ground, in small mound of stone, and from which a:


6" Fir bears N79°W 4.8 ft.; scribed $\frac{1}{4}$ " S9 BT RE2311.

10" Fir bears S42°W 9.9 ft.; scribed $\frac{1}{4}$ " S16 BT.

Set 4"x3"x72" white painted Cedar post 2 ft. SE of pipe.
Oregon State Board of Forestry metal location poster on 10" Fir BT.
Also poster on 4"x3"x72" white painted Cedar post on W edge road approximately 1120 ft. W of corner.

Dated June 9, 1955.

Restored by Richard A. Morris under my direction.
Richard A. Morris, Engineering Aide



Present and witnessed by Jack Wanek
Forrest Logan
Robert Sturm