

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One quarter corner common to Section 6 (West side)
T. 1 S., R. 8 W., W.M., Tillamook County, Oregon.

ORIGINAL

18" x 14" x 7" stone, now missing, from which a:

12" Spruce bears N72°E 16 lks.; now 36"x6" stub in place,
log 20 ft. downhill with scribes $\frac{1}{4}$ S BT.

4" Elder bears N79°W 38 lks.; now missing, sprouts nearby

RESTORED

Set $1\frac{1}{2}$ " x 36" galvanized iron pipe with 3" bronze cap
marked "OREGON STATE BOARD OF FORESTRY $\frac{1}{4}$ S6 1955 RE 2311,"
33 inches in ground, in mound of stone, and from which a:

16" Hemlock bears N46°E 26.6 ft.; scribed $\frac{1}{4}$ S 6 BT RE 2311.

Set 4"x4"x72" white painted Cedar post 1 ft. NE of pipe.
Oregon State Board of Forestry metal location poster on 16"
Spruce N38°W 32.9 ft.

Dated June 22, 1955

Restored by Arnold G. Gibson under my direction.
Arnold G. Gibson, Assistant Engineer



Present and witnessed by Lloyd Geraths
Forrest Logan
Robert Sturm

Book I