

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One quarter corner common to Section 31 (base line)
Township 1 North, Range 6 West, W.M., Tillamook County,
Oregon.

ORIGINAL

Post (missing) from which a:

- 8" hemlock bears S3°W 28 lks.; now 25", scribe B visible, rest unexposed.
- 10" hemlock bears N33°E 42 lks.; now 13" rotted stub 1' high, scribes and face rotted off.

RESTORED

Var. 21½°E

Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY BL ¼ S31 1956 RS 359," 34 inches in ground, in mound of stone, and from which a:



51" Fir bears N35°E 29.3 ft.; scribed ¼ S31 BL BT RS 359.

Oregon State Board of Forestry metal location poster on 51" Fir BT.

Set 4" x 4" x 72" white painted Cedar post 2 ft. SE of pipe.

Dated August 17, 1956.

Restored by Richard Morris under my direction.
Richard Morris, Transitman



Present and witnessed by Robert Strum
Lloyd Geraths