

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One Quarter corner common to Sections 13 and 24, T. 2N., R. 8W., W.M., Tillamook County, Oregon.

ORIGINAL

Basalt stone 18" x 12" x 6" (Missing) from which a:

5" Hemlock bears N30°E 35 lks.; now missing, position falls in slide area.

15" Hemlock bears South 18 lks.; now 34" snag, scribes BT visible on burnt face, upper face burnt out.

RESTORED

Var. 21½°E.

Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY 1/4 S13 S24 1957 RS401," 35" in ground, in mound of stone, and from which a:

28" Fir snag bears S74°W 3.1 ft.; scribed 1/4 S24 BT.

50" Fir snag bears N53°E 10.4 ft.; scribed 1/4 S13 BT RS 401

Oregon State Board of Forestry metal location poster on 50" Fir snag BT.


Set 4" x 4" x 60" white painted cedar post 1.5' SE

Dated September 4, 1957.

Restored by



Richard A. Morris



Present and witnessed by Robert Sturm
Harold Russell.