

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One Quarter corner common to Sections 20 and 29,  
T. 3N, R. 6W, W.M., Tillamook County, Oregon.

ORIGINAL

Stake (now missing) from which a:

5' Fir bears S22°15'E. 30 lks.; now 54" stump, scribes BT visible, upper face cut off when logged.

15" Hemlock bears N33°15'W. 4 lks.; now 28" stub 7' high, face and scribes rotted off.

RESTORED

Var. 21½° E

Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY 1/4 S20 S29 1957 RS401," 33 inches in ground, in mound of stone, and from which a:

6" Fir bears S38½° E 8.3 ft.; scribed 1/4 S29 BT RS 401

8" Fir bears N44° W 19.9 ft.; scribed 1/4 S20 BT.

Oregon State Board of Forestry metal location poster on 6" Fir BT.


Set 4" x 4" x 60" white painted cedar post 1.5' S.W. of pipe.

Dated October 25, 1957

Restored by



*Richard A. Morris*



Present and witnessed by Robert Sturm