CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY One Quarter corner common to Sections 3 and 10, T: 1S, R. 9W, W.M., Tillamook County, Oregon.

ORIGINAL

6" Hemlock (missing) from which a:

30 Hemlock bears N55E 40 lks.; now 50 stump, scribe S visible on on partly exposed face.

Hemlock bears N342W 84 lks.; now 44" stump, face and scribes cut off when logged.

RESTORED

Var. 211E

Set 15" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY 1/4 S3 S10 1958 RS401, 33 inches in ground, in mound of stone, and from which a:

9 Hemlock bears S84E 15.6 ft.; scribed 1/4 S10 BT.
21 Hemlock bears N84W 36.8 ft.; scribed 1/4 S3 BT RS 401.

Oregon State Board of Forestry metal location poster on 24" Hemlock S73W 23.6 Ft. Set 4" x 4" x 72" white painted Cedar post 1.7 Ft. N.E. of pipe.

Dated March 6, 1958.

Restored by

REGISTERED
OREGON
LAND SURVEYOR

Richard A. Morris

401

Present and witnessed by Robert Sturm
Harold Russell
Jack Willford

Book I

X 美。

5