CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY
One Quarter corner common to Section 31 (Base Line)
T. 1N, R. 8W, W.M., Tillamook County, Oregon.

ORIGINAL

Post (now missing, found 2" iron pipe in place) from which a:

24" Hemlock bears S37W 37 lks.; now 33" stub 15th high, scribes 1/4S visible.

6" Maple bears N19E 93 lks.; now missing, vine maple clumps.

No evidence of resurveys of 1884 and 1893 found.

RESTORED

Erected mound of stone around above pipe, from which a:

7" Alder bears N33½E 60.5 ft.; scribed in bark, 1/4 S31 BT. 8" Alder bears N54W 67.8 ft.; scribed in bark, 1/4 S31 BT RS 401.

Oregon State Board of Forestry metal location poster on 8" Alder BT. Set 4" x 4" x 48" white painted Cedar post 1.5' S.E. of pipe.

Dated April 4, 1958.

Restored by

REGISTERED
OREGON
LAND SULVEYOR

Suchon Of Morris

MAY 10, 1957
Richard A. Morris

401

Present and witnessed by Robert Sturm Harold Russell

Book I

3/1

321