

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One Quarter corner common to Sections 15 and 22,
T. 2S., R. 9W., W.M., Tillamook County, Oregon.

ORIGINAL

Post (now missing) from which a:

- 40" Hemlock bears S33W 32 lks.; now missing.
- 40" Spruce bears N20W 20 lks.; now missing.

RESTORED by W. E. Anderson 1925

Spruce limb (now missing, found 1" x 20" Iron Pipe out of place from which a:

- 40" Spruce bears N80E 13.4 ft.; now 73" Spruce, portion of scribe visible, rest unexposed.
- 70" Dead Snag bears N80W 22.8 ft.; now down and badly decayed, roots and root hole in place.

RESTORED

Var. 21 $\frac{1}{2}$ E


Set above 1" x 20" iron pipe in place 18 inches in ground, and from which a:

- 73" Spruce (see above) bears N80E 13.4 ft.; scribed BT on overgrowth.
- 60" Hemlock bears S3W 51.8 ft.; scribed 1/4 S22 BT RS401.


Oregon State Board of Forestry metal location poster on 73" Spruce BT.
Set 4" x 4" x 60" white painted Cedar post 1.5' S.E. of pipe.

Dated June 23, 1958

Restored by Robert Sturm under my direction.
Robert Sturm, Compassman



Richard A. Morris



Present and witnessed by Harold Russell

Book I

342

342

342