

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One Quarter corner common to Sections 9 and 10,
T2N, R8W, W.M., Tillamook County, Oregon.

ORIGINAL

Basalt Stone 15" x 10" x 5" (missing, corner point falls in slide area)
from which a:

28" Fir bears N81E 32 lks.; now 32" stump, scribes 1/4 S visible,
lower face unexposed.

8" Hemlock bears N76W 15 lks.; now missing, point falls in slide
area.

RESTORED

Var. 21 1/2 E

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON
STATE BOARD OF FORESTRY 1/4 S9 S10 1959 RS401", 30 inches in ground,
and from which a:


36" Fir stump bears S76W 59.4 ft.; scribed 1/4 S9 BT RS401.

Oregon State Board of Forestry metal location poster on original 28"
Fir BT.


Set 4" x 4" x 48" white painted Cedar post 1.2 ft. N.E. of pipe.

Dated August 4, 1959

Restored by Harold J. Russell under my direction.
Harold Russell, Eng. Tech. I



Richard A. Morris



Present and witnessed by E. Nylund
D. Jones