CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One Quarter corner common to Sections 15 and 22, T3N, R9W, W.M., Tillamook County, Oregon.

ORIGINAL

Marked South face of bluff with X 1/4 (marks now missing) from which a: Summit of S. spur of hill-rock ledge bears East 47 lks.; now in place. NOTE: This point as restored below is the only place along the cliff which is 47 links West of the ledge summit.

RESTORED

Var. 212E

At a point 47 lks. W. of above spur hill-rock ledge and bottom of rock bluff on rock face facing South, marked X 1/4 from which a:

Rock face bears S162E 13.0 ft.; scribed B0. 5 Fir bears S15 W 69.1 ft.; scribed 1/4 S22 BT RS401.

Oregon State Board of Forestry metal location poster on 5" Fir BT. Set 4" x 4" x 60" white painted Cedar post 3.4' S 75E.

Dated May 6, 1960

Restored by

REGISTERED OREGON LAND SURVEYOR

> Richard A. Morris 401

Present and witnessed by R. Cop

G. Nylund