

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 14, 15, 22 and 23, T3N, R9W, W.M., Tillamook County, Oregon.

ORIGINAL

24" Alder (now missing) from which a:

8" V. Maple bears N27E 24 lks.; now missing.

26" Alder bears S46E 7 lks.; now missing.

26" Maple bears S32W 26 lks.; now rotted out shell with clump of Maples growing out of it.

27" Cedar bears N29W 16 lks.; now 24" rotted uproot, root hole in place, face and scribes rotted away.

Brook, 1 lk. wide, course E bears South 5.15 chs.; now in place.

Brook, 3 lks. wide, course S20E bears North 4.27 chs.; now in place.

Creek, 6 lks. wide, course S20E bears East 2.50 chs.; now in place.

RESTORED

Var. 21<sup>1/2</sup>E

Set 1<sup>1/2</sup>" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T3N R9W S15 S14 S22 S23 1960 RS401", 32 inches in ground, in mound of stone, and from which a:

12" Cedar bears N14W 30.9 ft.; scribed T3N R9W S15 BT.

11" Fir bears N61E 30.9 ft.; scribed T3N R9W S14 BT.

22" Fir bears S71E 41.8 ft.; scribed T3N R9W S23 BT RS401.

18" Fir bears S51W 48.2 ft.; scribed T3N R9W S22 BT.

Oregon State Board of Forestry metal location poster on 12" Cedar BT.


Set 4" x 4" x 60" white painted Fir post 1.1' N.W. of pipe.

Dated April 26, 1960

Restored by



*Richard A. Morris*



Present and witnessed by R. Cop  
G. Nylund  
M. Flippen