**CHAINS** 

RESTORED CORNER FOR STATE OF OREGON-DEPARTMENT OF FORESTRY

Section corner common to Sections 1, 2, 11 and 12, T.3N, R.10W, W.M., Tillamook County, Oregon.

ORIGINAL

Post (now missing) from which a:

6" Hemlock bears N31W 13 lks.; now missing.

6" Hemlock bears SlOW 24 lks.; now missing.

6" Hemlock bears S45°E 45 lks.; now missing.

90" Spruce bears N20°E 27 lks.; now 88" snag, no scribes remaining. Original Lineblaze bears North 206 ft.; on 72" Spruce snag.

Original Lineblaze bears N87°28'W. 350 ft.; on 50" Fir stump. Lineblaze bears East 64 ft.; on 60" Hemlock stump.

Railroad Grade bears West 726 ft.; Course SlOoE, as recorded in railroad description at county court house.

RESTORED

Var. 21&E

Set 15" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T3N RIOW 1, 2, 11, 12, 1962 RS 401", 32 inches in ground, and from which a:

27 Hemlock bears N50°W 34.0 ft.; scribed T3N R10W S2BT RS401.

22" Spruce bears S65½°E 46.4 ft.; scribed T3N R10W S12 BT. 36" Spruce bears S2½°W 50.7 ft.; scribed T3N R10W S11 BT. 26" Spruce bears N62°E 74.1 ft.; scribed T3N R10W S1 BT.

Found 2" pipe West 201.6 ft.

Oregon State Forestry Department metal location poster on 27" Hem. BT. Set 4" x 4" x 50" white painted Cedar post 1.0 ft. SE of corner pipe.

Dated March 27, 1963.

Restored by

Billy E. Davis Transitman

under my direction.

Present and witnessed by A. Duncan

D. Fletcher

REGISTERED OREGON LAND SURVEYOR

Richard A. Morris