

County Surveyor's Record, Tillamook County Oregon

CHAINS

RESTORED CORNER FOR STATE OF OREGON-DEPARTMENT OF FORESTRY

One Quarter corner common to Sections 8 and 17, T3S, R8W, W.M.
Tillamook County, Oregon.

*1/4 cor
S. 30m
8-3-58*

ORIGINAL

Basalt stone 14" x 12" x 8" (now in place, marks decayed away) from which a:

- 5" Hemlock bears N4E 30 lks.; now missing, 11" Alder growing in place.
- 10" Hemlock bears S41E 20 lks.; now missing, possible root hole in place.

RESTORED by County Surveyor, November 25, 1903

Barberry stake (missing) from which a:

- 18" Fir bears S63W 2 lks.; now 42" stump (bears S23 $\frac{1}{2}$ W 4.7') face unexposed, faces toward above original corner stone.
- 6" Alder bears N13E 39 lks.; now 19.8', scribe mark exposed.

RESTORED

Var. 21 $\frac{1}{2}$ E

Set 1 $\frac{1}{2}$ " x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY 1/4 S8 S17 1961 RS401", 34 inches in ground, in place of badly decayed corner stone, in small mound of stone, and from which a:

- 16" Hemlock bears N46W 19.9 ft.; scribed 1/4 S8 BT.
- 16" Hemlock bears S40 $\frac{1}{2}$ E 35.5 ft.; scribed 1/4 S17 BT RS401.

Oregon State Forestry Department metal location poster on 16" Hemlock BT N46W.

Set 4" x 4" x 54" white painted Cedar post 1.0 ft. S.W. of corner pipe.

Dated April 6, 1962

Restored by Harold J Russell under my direction.
Harold Russell, Engineering Technician

Present and witnessed by E. Nylund
A. Duncan

