CHAINS

RESTORED FOR OREGON STATE BOARD OF FORESTRY

Quarter corner common to sections 3 and 34, Townships 1 & 2 South, Range 7 West, W.M., Tillamook County, Oregon.

ORIGINAL

Post, now missing, from which a:

16" Hemlock bears N44°30°E 63 lks; now 34" snag N42E, didn't expose face.

24" Hemlock bears S03°30'W 37 lks; now 44" snag S01E, scribe mark 1/4 S exposed.

RESTORED CORNER AND BEARING TREES

Set 12" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY 1/4 S34 S3 1952 2311," 22" in ground, from which a:

72" Fir snag bears N19W 42.6'; scribed 1/4 S34 BT. 84" Fir stub 25' high bears S16E 41.9'; scribed 1/4 S3 BT RE 2311.

Placed en Oregon State Board of Forestry metallocation poster on 84" Fir stub BT and marked it: Sec 3 T2S R7W 1/4 Cor 41.9 ft. N16W.

Dated May 6, 1952.

This corner was restored by under my direction.

Don D. Davis Assistant Forest Engineer

Present and witnessed by

Richard A. Morris

Compassman

Present and witnessed by

Robert A. Young

-Chainman

PAOK 2