

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One-quarter corner common to sections 23 and 24, Township 1 South, Range 8 West, W.M., Tillamook County, Oregon.

ORIGINAL

Post, now missing, from which a:

- 14" Hemlock bears N42W 47 lks.; now 36" stub 20" high N34W, exposed scribe marks 1/4 S.
- 10" Hemlock bears S41E 20 lks.; now 16" stub 15" high, exposed scribe marks BT.

RESTORED CORNER AND WITNESSED CORNER POINT

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY 1/4 S23 S24 1952 2311," 2 1/2" in ground, from which a:

- 68" Fir snag bears S29W 57.2°; scribed 1/4 S23 BT RE2311.
- 3" Fir bears N77E 52.8°; scribed S24 BT.

Placed an Oregon State Board of Forestry metal location poster on 68" Fir snag BT and marked it: Sec 23 T1S R8W 1/4 Cor 57.2 Ft. N29°E.

Dated December 12, 1952.

This corner was restored by Don D. Davis,
Don D. Davis Assistant Forest Engineer
under my direction.



Present and witnessed by Gerald M. Schwalen, Chairman.