CHAINS

## RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 8, 9, 16 and 17, Township 2 North, Range 6 West, W.M., Tillamook and Washington Counties, Cregon

## ORIGINAL

Stone 14" x 9" x 5", in place, 4 notches on South and East edges, from which a:

> 12" Cedar bears N26E 42 1ks.; now 12" snag, face burned off.

24" Cedar bears  $$80\frac{1}{2}$ E 38 lks.;

now 28" uproot, no face. 24" Fir bears S27W 18 lks.; now 36" uprooted stump, no face.

30" Cedar bears N52W 25 lks.; now 36" uproot, part of scribe mark visible.

## RESTORED

Set 13" x 36" galvanized iron pipe with 3" Bronze cap marked "OREGON STATE BOARD OF FORESTRY T2N R6W S8 S9 S16 S17 1953 2311," 32 inches in ground, in mound of stone, and from which a:

> 37" Fir stump bears N30W 79.0 ft.; scribed T2N R6W S8 BT.

29" Fir stump bears N17 2E 31.7 ft.; scribed T2N R6W S9 BT RE 2311.

32" Fir stump bears S47W 106.8 ft.; scribed T2N R6W S17 BT.

43" Cedar stump bears S76E 53.9 ft.; scribed T2N R6W S16 BT.

Dated November 12, 1953.

Restored by Compassman my direction. Richard Morris.

> RED PROFES NGINEER

Present and witnessed by Carl Vold

Robert Schumacher

BOOK