CHAINS

REESTABLISHED CORNERS FOR OREGON STATE BOARD OF FORESTRY

One Quarter corner common to Sections 19 and 24, TlN, R9 and 10W, W.M., Tillamook County, Oregon.

REESTABLISHED

Var. 212E

Set 13" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY 1/4 S24 S19 1959 RS401", 34 inches in ground, in mound of stone, and from which a:

11" Hemlock bears N182W 28.9 ft.; scribed 1/4 S24 BT.
17" Fir bears S 0°45'E 29.0 ft.; scribed 1/4 S19 BT RS401.

Oregon State Board of Forestry metal location poster on 17" Fir BT. Set 4" x 4" x 60" white painted Cedar post 1.0' S.W. of pipe:

Present and witnessed by R. Cop

One Quarter corner common to Sections 25 and 36, TlN, R. 10W, W.M., Tillamook County, Oregon.

ORIGINAL

(No evidence of original corner found)

Ridge bears East 222 lks.; now in place.

REESTABLISHED

Var. 21 E

At a point on the line between Sec. Cor. 25, 26, 35, 36 and Sec. Cor. 25, 30, 31 and 36, and 2.22 chains N89°53'58"W from above Ridge top set 1½" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY 1/4 S25 S36 1959 RS401", 30 inches in ground, in mound of stone, and from which a:

7" Fir bears S11E 79.6 ft.; scribed 1/4 S36 BT RS401. 10" Fir bears N60E 90.7 ft.; scribed 1/4 S25 BT.

Oregon State Board of Forestry metal location poster on 10" Fir BT. Set 4" x 4" x 60" white painted Cedar post 1.0° S.E. of pipe.

Present and witnessed by H. Russell

E. Nylund

D. Jones

Dated December 31, 1959

Reestablished by

REGISTERED

OREGON

LAND SURVEYOR

MAY 10 1957

Richard A. Mozois

7401

BOOK 2

y

44(