

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 25, 26, 35 and 36, T1N, R10W, W.M., Tillamook County, Oregon.

ORIGINAL

Post (missing) from which a:

- 16" Alder bears N42E 60 lks.; now 24" stump, no scribes or face visible.
- 16" Alder bears N37W 16 lks.; now missing.
- 24" Alder bears S58E 38 lks.; now missing.
- 16" Alder bears S5W 9 lks.; now 20" uproot, roots and root hole in place, scribes and face rotted away.

- Foot of hill bears West 6 chs.; now in place;
- Spur bears North 2.50 chs.; now in place.
- 10 Lk. wide creek, course S60W, bears North 14.50 chs.; now in place.

RESTORED

Var. 21 1/2 E


Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T1N R10W S26 S25 S35 S36 1959 RS401", 34 inches in ground, and from which a:

- 62" Spruce bears S2 1/2 W 84.5 ft.; scribed T1N R10W S35 BT RS401.
- 24" Spruce bears S78W 68.3 ft.; scribed T1N R10W S35 BT.

Oregon State Board of Forestry metal location poster on 62" Spruce BT.
Set 4" x 4" x 60" white painted Cedar post 1.0' N.E. of pipe.

Dated December 31, 1959

Restored by



Present and witnessed by H. Russell
R. Cop
E. Nylund
D. Jones