CHAINS

RESTORED CORNERS FOR CREGON STATE BOARD OF FORESTRY North one-sixteenth corner common to Sections 28 and 29, T3S, R9W, W.M., Tillamook County, Oregon.

ORIGINAL By U. G. Jackson, County Surveyor, Feb. 1913

Post (found in place, scribes 1/16 remaining) from which a:

10 Fir bears 34015 W 46.1 Ft.; found in place, now 38" stump.

RESTORED

Set 12" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY N 1/16 S28 S29 1961 RE2311", 28 inches in ground, and from which a:

15" Alder bears N85°E 28.0 ft.; scribed N 1/16 S28 BT. 28" Fir bears N10°W 89.0 ft.; scribed N 1/16 S29 BT RE2311.

Oregon State Board of Forestry metal location poster on 5" Alder N2320W 6.1 ft.

Set 4" x 4" x 72" white painted Cedar post 1 ft. NE of corner pipe.

Dated June 7, 1961

Restored by

Billy E. Davis, Transitman

under my direction.

D PROF

ENGINEER

2311

ole

ZUIS W.

GREGON

Present and witnessed by D. M. McConnell

H. Baughn

\* \* \* \* \* \* \* \*

One Quarter corner common to Sections 20 and 21, T3S, R9W, W.M., Tillamook County, Oregon.

ORIGINAL

Post (now missing) from which a:

60 Spruce bears S37°W 59 lks.; now missing.

40 Fir bears S32°E 64 lks.; now missing.

144 Spruce line tree bears North 17.25 chs. found in place, now rotted stump.

RESTORED by unknown party

3" x 3" x 24" scribed stake (found in place scribes 1/ remaining)

RESTORED

Set 12" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY 1/4 S20 S21 1961 RE2311", 32 inches in ground, and from which a:

10" Spruce bears S86°W 66.3 ft.; scribed 1/4 S20 BT.
17" Alder bears N18½E 19.4 ft.; scribed 1/4 S21 BT RE2311.

Oregon State Board of Forestry metal location poster on 17" BT. Set 4" x 4" x 72" white painted Cedar post 1 ft. SW of corner pipe.

Dated June 7, 1961

under my direction.

Billy Ex Davis, Transitman

Present and witnessed by D. McConnell, H. Baughn.

Jouis Lellmort

519

5/9