CHAINS RESTORED CORNER FOR STATE OF OREGON-DEPARTMENT OF FORESTRY 100 Township corner common to Sections 31, 36, 1 and 6, T3 and 4S, R9 and 10W, W.M., Tillamook County, Oregon. ORIGINAL Post (now missing) from which a: 5" Fir bears M17°E 238 1ks.; now 20" badly rotted 2' high stub, backcast of scribe found inside, rest rotted away. 5" Fir bears N74°W 93 lks.; now missing, open field. 15" Fir bears S82°W 159 lks.; now missing, open field. 4" Maple bears S58°E 78 lks.; now missing, open field. RESTORATION by County Surveyor Post (now missing) from which a: 8" Fir (original) bears N17°E 238 lks.; See Above. 16" Hem. bears S392°W 258 1ks.; now 32" Hem. stub, backcast of scribe S found inside on partly exposed face (now bears S43°W 203.5 ft.). RESTORED Var. 212°E Set 12" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T3S T4S R9W RIOW S31 S36 S1 S6 1965 RS401", 32 inches in ground, in mound of rock, and from which a: 14" Fir bears N89 8/4°W 214.5 ft.; scribed T3S R10W S36 BT. 19" Fir bears N50°E 140.2 ft.; scribed T3S R9W S31 BT RS401. 18" Fir bears S482°E 252.4 ft.; scribed T4S R9W S6 BT. Corner is 4.5° South of an East and West fence line. Set 4" x 4" x 60" white painted Cedar post 1.2 ft. NE of corner pipe. Oregon State Forestry Department metal location poster on 14" Fir BT. Dated June 10, 1965 101 under my direction Restored Present and witnessed by A. Duncan REGISTERED OREGON D SURVEYOR MAY 10. 1959 Richard A. Morris 401

504

BOOK 2

Bunk I