Dependent Resurvey, Portion of Subdivisional Lines, T. 4 S., R. 7 W.

CHAINS

Bottom of descent, slopes W.; asc. 115 ft. along broken 67.00 W. slope, changing to SW. slope.

79.28

The cor. of secs. 7, 8, 17, and 18, monumented with an unmarked basalt stone, $16 \times 10 \times 8$ ins., firmly set 8 ins. in the ground. This stone was found by Mervin Whitmore, Deputy County Surveyor, in 1953, and was used by him for the corner. The stone is located at the intersection of old line blazes which extend N., E., and W., from this point, and is accepted as the best available evidence of the original corner.

At the corner point

Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the ground, and in a mound of stone, 2 ft. base, to top, with brass cap mkd.

> T45R7W S 7 | S 8 S 18 S 17 1965

from which

- A fir, 10 ins. diam., bears N. 85° E., 142 1ks. dist., mkd. T4S R7W S8 BT.
- A fir, 35 ins. diam., bears S. 1° E., 37 lks. dist., mkd. T4S R7W S17 BT.
- A fir, 23 ins. diam., bears S. 66° W., 42 lks. dist., mkd. T4S R7W S18 BT.
- A fir, 30 ins. diam., bears N. $28\frac{1}{2}^{\circ}$ W., $59\frac{1}{2}$ 1ks. dist., mkd. T4S R7W S7 BT.

Deposit the corner stone alongside the iron post.

The corner is located on a spur, slopes NW.

Land, mountainous. Soil, rocky clay. Timber, fir, alder, cascara, cedar, hemlock and spruce; undergrowth, vine maple, salal, fern, salmonberry, huckleberry and Oregon grape.

From the cor. of secs. 8, 9, 16, and 17.

N. 89° 34' W., bet. secs. 8 and 17.

Descend 175 ft. over SW. slope, through heavy timber and dense undergrowth.

- Dirt road, 10 lks. wide, bears N. 25° W. and S. 25° E. 5.50
- Bottom of descent, slopes S. 30° W.; asc. 10 ft. over 6.30 E. slope.
- Top of ascent, slopes S. 15° W.; desc. 100 ft., over W. 8.30 slope.
- Spring, drains S. 35° W.; desc. 70 ft. over SW. slope. 13.80
- Point for the E 1/16 sec. cor. of secs. 8 and 17. 19.73

Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the ground, with brass cap mkd.

800K 3