County Surveyor's Record, Tillamook County, Oregon

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

(Reference FSH 5681.65)

History of original corner establishment:

This corner was established in 1882 by General Land Office (William P. Wright, surveyor).

It was reestablished in 1956 by John C. Carlich (ORLS 287)

DIAGRAM T5S, R1OW, W.M.

Description of corner evidence found:

Found 1 inch by 24 inch iron pipe for 4 corner to Sections 16 and 21 with a $4 \times 4 \times 48$ inch wooden post alongside pipe.

From which:

A fir, 14 inches in diameter bears N64E, 61.4 feet distance

A hemlock, 12 inches in diameter bears due west, 46.7 feet slope distance

Description of monument and accessories I established to perpetuate the original location of this corner

At the corner point set a 2 inch by 30 inch cement filled iron pipe with a brass cap marked

T5s Rlow

<u>16</u>

1968

ORLS 650

From which:

An alder, 14 inches in diameter bears S85½E, 17.9 feet distance Bark Scribed N 1/4 S 21 BT

An alder, 18 inches in diameter bears S56 E, 55.4 feet distance Bark Scribed N 4 S 21 BT Deposited iron pipe and wooden post beside the monument.

U.S.F.S. bearing tree signs were placed on all BT's facing the monument

CS . O by (DEPUTY)

REGISTERED OREGON LAND SURVEYOR

auc JULY 10, 1964 TOM O. McCULLOU

650

300K 3

Form R6-5680-182 (12/63)