

And Associates

P. D. BOX 857 — CORVALLIS, DREGON 97330

INCORPORATED

TELEPHONE 503 752-2636

December 18, 1968

Mr. Harold J. Russell District Engineer 4907 Third Street Tillamook, Oregon 97141

Dear Jim:

Per my telephone conversation with Dick Morris on November 15, 1968, regarding my reestablished North quarter corner and Northwest section corner of Section 2, T4S, R7W, W.M., I gave him permission to have these corners destroyed since you have found the original North quarter corner of the above section.

Please send me the official plat upon completion of this project.

Hope this does the job for you.

Yours very truly,

McCullough, BRYANT & ASSOCIATES

I can.

Tom O. McCullough

dq:MOT

County Surveyor's Record, Tillamook County, Oregon

CHAINS

RESTORED CORNER FOR STATE OF OREGON DEPARTMENT OF FORESTRY

One quarter corner common to Sections 35 and 2, Township 3 & 4 South, Range 7 West, Willamette Meridian, Tillamook County, Oregon.

ORIGINAL

Stone 14" x 9" x 7" (in place /4 on North face).

RESTORED

Var. $2l^{\frac{1}{2}}E$

Marked X in top of original stone and erected mound of stone around it, from which a:

llu Fir bears N la W 15.5 ft.; scribed l/L S3L BT RS 707.
13" Fir bears S llu 3/L W 4.3 ft.; scribed l/L S2 BT.

I Destroyed corner re-established by T. O. McCullough. Point bears S 28° 03' E 18.05 ft.

BOOK 3

Set 6" x 6" x 48" Fir limb 1.0 ft. NW of corner stone.

Oregon State Forestry Department metal location poster on 13" Fir BT.

Russell

Dated December 10, 1968.

Restored by

REGISTERED O R E G O N LAND SURVEYOR

JULY 9, 1965 HAROLD J. RUSSELL 707

Ceresed

Present and witnessed by C. Curl J. Grace.

Book 3