County Surveyor's Record, Tillamook County, Oregon

CHAINS

RESTORED CORNER FOR STATE OF OREGON-DEPARTMENT OF FORESTRY

One quarter corner common to Sections 27 and 28, T3S, R7W, W.M., Tillamook County, Oregon.

ORIGINAL

Stone, $18^{11} \times 8^{11} \times 6^{11}$ (found in place 12^{11} in ground, $\frac{1}{4}$ on West face).

RESTORED

Var. 2120E

Marked X in top of original stone, from which a:

20" Hemlock bears $S47_{2}^{10}$ E 26.2 ft.; scribed $\frac{1}{4}$ S27 BT RS 707. 15" Hemlock bears $S12_{2}^{10}$ W 37.4 ft.; scribed $\frac{1}{4}$ S28 BT. Nestucca River Road bears E approx. 110 ft.

Set $4^{11} \times 4^{11} \times 50^{11}$; white painted Cedar post 1.0 ft. SW of corner stone.

Oregon State Forestry Department metal location poster on 15th Hemlock BT.

Dated March 31, 1969.

Restored by _______

under my direction.

Charles Curl, Engineer technician

Present and witnessed by Jerry Grace.

REGISTERED O R E G O N LAND SURVEYOR

JULY A, 1965 HAROLD J. RUSSELL 707

BOOK 3