FINAL FIELD NOTES FOREST SERVICE SURVEY CONTRACT #01656

Feet

From the corner of Sections 2, 3, 10 and 11 in T 5 S, R 10 W, which is monumented by a Brass Cap firmly set, witnessed as described in the official records. Ascend south along the line between Sections 10 and 11 along clear cut boundary.

- 53 Top of low ridge, descend.
- 320 Begin ascend.
- 850 Summit of flat ridge, begin descend.
- 1.323.84 Point for N 1/16 corner, Sec. 10/11 west 16 ft. of an old wire fence. Set 2"x 30" G.I.P. 3" brass cap with top marked.

N 1/16 10/11 1969 PE 2301 ORE

I scribed

from which /a 34 in. D fir bears N 35° W, 39.3 ft., mkd. N 1/16 S 10 BT.

a 27 in. spruce bears S 71° E, 58.8 ft., mkd. N 1/16 S 11 BT. old $1\frac{1}{2}$ in. corner pipe bears N 51° W 3.6 ft.

- 1,780 Gravel road rng. E and W. Continue descent through vine maple, alder and salmon berry.
- 2,200 Begin ascent through dense brush.
- 2,647.68 Point for standard \(\frac{1}{4}\) sec. cor. of sec. 10, 11; 18.4 ft. S 12 W from old fence corner.

Set 2x30 in. G.I.P. 3 in. brass cap with top mkd.

‡ S 10/11 1969 PE2301 ORE

from which I scribed:

- a 11" diam. D-fir bears S 60 W, 23.3 ft. mkd $\frac{1}{4}$ S S 10 BT.
- a 24 in. dia. Spruce bears S 69° E, 35.1 ft. mkd. $\frac{1}{4}$ S S 11 BT.

land slopes down to the West cutting bdy. rng. E and W.

- 2,700 Nearly level through spruce stand with dense underbrush in spots.
- 2,800 Begin descent through timber with dense underbrush in spots.
- 3,610 Small creek in bottom of steep draw. Begin steep ascent.
- 3.750 top of bench in timber.

S 1/16 10/11 1969 PE 2301 ORE

from which I scribed:

an 18 in. spruce bears N 2° W, 13.7 ft., mkd. S 1/16 S 10 BT

800K 3 a 16 in. spruce with 3 equal tops bears S 46° E, 18.4 ft., mkd. S 1/16 S 11 BT.

continuing across flat with scattered timber and brush