## History of original corner establishment:

Corner was first established in October of 1890 through a contract from the General Land Office. Post 4 feet long, 4 inches square and 2 feet deep was set for the 2 corner marked 2 s on the north side from which

DIAGI	DIAGRAM				
Т 3	S	R	10	W	
埕 —	6 7	 L93	33		

A spruce 30 inches in diameter brs N26E 28 lks. mkd. ½ S BT

A hemlock 24 inches in diameter brs S73E 1ks. mkd. & S BT

In 1933 an iron post with a brass cap was set for the corner.

## Description of corner evidence found:

Found a brass cap for the corner buried in 6 inches of mud from which

A 25 inch hemlock stump brs S72E 19.3 ft; Portion of scribing still visible. > B,
Two Forest Service tags on stump.

A downed 30 inch spruce bears N50E 22.3 feet. Face scarred over; Forest Service tag visible.

## Description of monument and accessories I established to perpetuate the original location of this corner

Set a 6 foot steel post with Forest Service boundary sign facing south at corner point. Also set similar post 5 feet north facing to the west. From the corner I established a new BT

A 4 inch spruce brs N41W 15.9 feet scribed  $\frac{1}{4}$  S 6 BT 650 Forest Service bearing tree tag on the BT

REGISTERED
OREGON
LAND SUBVEYOR

Tom O. W Chilfur

JULY 10, 1964

TOM O. McCULLOUGH
650

Office of	County of
State of , 1-h	nereby certify that the within instrument was filed in this office
	(DEPUTY)
(COUNTY OFFICIAL)	(DEPUTY)