


CERTIFIED RECORD OF LAND CORNER MONUMENT

History of original corner establishment:

Corner set in 1880 by Caudle - built stone mound.
Corner was re-established in 1970 by J. Prochnau



Description of corner evidence found:

Found 2"x30" iron pipe with brass cap marked

$\frac{1}{4}$
S 22 | 23

1970
4185 from which

old post with $\frac{1}{4}$ scribed brs. N40W 4.4 ft
20" fir brs. N75E 8.7 ft - with tag @ scribing visible
17" fir brs. S84W 6.7 ft - with tag - scribing visible

Description of monument and accessories established to perpetuate the original location of this corner

None

(PROPORTION POINT
SET BY B-592)

REGISTERED
OREGON
LAND SURVEYOR

William R. Rust

JULY 17, 1970
WILLIAM R. RUST
936

Office of COUNTY SURVEYOR County of TILLAMOOK
State of OREGON, I hereby certify that the within instrument was filed in this office
for record on the 18th day of SEPTEMBER, 1970 at o'clock m., (signed)
J. Prochnau by William R. Rust
(COUNTY OFFICIAL) (DEPUTY)