RECORD OF LAND CORNER MONUMENTA

Corner originally set by Caudle in 1880. He set a post from

A 60" fir brs. west 20 lks.

A 50" fir brs. N60E 17 1ks.

M. Whitmore found corner in 1949.

DIAGRAM			
T	3S		
R9W	24	19	R8W

Description of corner evidence found:

Found a $\frac{1}{2}$ " iron pipe from which

> A 50" snag brs. N60E 13.3 feet scribing rotted off.

A 60" snag brs. west 10.2 feet scribing and old axe marks barely visible.

Description of monument and accessories I established to perpetuate the original location of this corner

Set a 2"x30" iron pipe with brass cap marked

Drove 1 pipe alongside brass cap

from which

A 19" fir brs. east 1.0 feet scribed 4 S19 BT 920

A 16" alder brs. S65W 11.5 feet bark scribed \(\frac{1}{4} \) S24 BT

Drove a steel fence post 3 feet west of corner with Forest Service boundary and attention signs facing south. Placed BT signs and painted all BTs.

Office of COONITY SURVEYOR County of TILLAMOOK State of OREGON.......... , I hereby certify that the within Instrument was filed in this office (COUNTY OFFICIAL)

REGISTERED

O R E G O N LAND SURVEYOR

388

JULY 17, 1970 RICHARD L. BRYANT 920

BOOK 3

Form R6-7100-57 (9/66)