CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

From Original Notes:

40.00 Set a post, 3 ft. long, 3 inches diam., 24 in. in ground for 1/4 corner marked 1/4 S on West face; from which:

e; from which: A fir, 24 inches diam., brs. N. 36° E. 16 lks. A fir, 48 inches diam., brs. S. 45° W. 154 lks.

DIAGRAM

T. 3 S., R. 8 W.

1/4

S 34 S 35

41.25 Spring branch, 1 lk. wide, runs E.; asc. 100 feet to

47.00 Top of hill, bears NE and SW; undulating.

Description of corner evidence found:

Found remnants of "24 inch fir N. 36° E., 16 lks." with no scribing visible. Found root depression and 50" fir windthrow snag at the call to the SW for "48 inch fir S 45° W. 154 lks.". Restored corner checks with the call to "spring branch 1 lk. wide" at 41.25 in old notes.

Description of monument and accessories I established to perpetuate the original location of this corner

Set a $2^{\prime\prime\prime}$ x $30^{\prime\prime\prime}$ iron post with brass cap marked

1/4 S 34 S 35 1971 OLS 816

from which:

a 36" fir bears S. 77° W. 64.8 feet, scribed BT 1/4 S 34; a 33" fir bears S. $88\frac{1}{2}$ ° E. 55.4 feet, scribed BT 1/4 S 35. (Bark Scribed)

All bearing trees are tagged and have a red band painted on them. Set a steel fence post 6 feet North of corner.

Office of Comment of Country of C

800K 5