

CERTIFIED RECORD OF LAND CORNER MONUMENTAT.

History of original corner establishment:

This corner was set originally in 1880 by Gaudle. He set a 12''x8''x7'' stone 80 chains North of the corner to section 27, 28, 33 and 34.

(Contract Survey)

Description of corner evidence found:

W. W. Hayes, Tillamook County Surveyor, restored this corner in 1887 by setting a 4"x4" Post. M. Whitmore in 1954 saw scribe marks "Yamhill" on the Eastside of post. He also saw marks "Tillamook Co. BT" on a 48" snag S.27°W., 41 feet S.D. He then marked 2 new BT's

36" fir N.47°W. 49 ft. SD, mkd. "T.5S., R.9W. S21BT" 36" fir N.56°E. 12⁵ft. SD, mkd. "T.5S., R.9W. S22BT"

I found a 4''x4'' wood post 2 feet above ground in poor condition tied to an iron axle located in a stone mound.

Description of monument and accessories I established to perpetuate the original location of this corner

I set a 2"x30" iron pipe with a flared bottom and a brasscap riveted to the top marked;

T.5S., R9W. <u>\$21</u> | \$22 <u>\$28</u> | \$27 <u>1971</u> O.L.S. 816

I tied to the existing BT's and old snag and scribed one new BT placing new tags and painting red bands on all of them:

42" fir N.470W. 49\(\) ft. (scar visible)
40" fir N.56°E. 11\(\) ft. (scar visible)
48" rotten stump S.27°W. 38\(\) ft.
14" fir S.83°W. 69\(\) ft., mkd. "T.5S., R.9W. S28BT"
No available trees to the S.E.

I built a small stone mound and reset the axle and post 1 foot East. I set 6 foot steel post with "Attention" and "Property Boundary" signs 3 feet West.

REGISTERED OREGON LAND SURVEYOR

Office of SUNTY SURVEYUR County of TULIANOOK JULY 17, 1970

State of ORSION I, I hereby certify that the within instrument was filed in this office 942

for record on the 12 day of OTOBER 1971, at 800 o'clock A.m., (signed)

(COUNTY OFFICIAL)

(COUNTY OFFICIAL)

Witnessed:

JUN 5

Set this 17th day of September 1971

M. Yinger

P. Wightman

197

Dk 5