CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Reference:

Closing Corner

32

6 5

Plat dated July 1973 by Timberland Services Inc. under my stamp.

Mistory of original corner establishment:

This corner was set by Albert P. Wilson under contract No. 555 dated June 25, 1890. He located this corner 79.60 chs. No 0° 04 1/2' W. of the corner to 6 5 . At that time he set a post:

"79.60 chs. Intersect 1st standard parallel S., 2.63 chs. E of old corner to Secs. 5, 6, 31, 32 which is a staone, set in the ground, 16"XX010" X 6" from which:

A Spruce, 9 ins diam., bears N. 20° W. 6 lks. mkd "T 6 S R 10 W S 31 BT"

At point of intersection, I set post 4 in. sq., 4 ft. long, 24 in. in ground, for closing corner to secs 5 & 6, mkd. "CC T 6 S R 10 W S 6 on S., S 6 on W and

DIAGRAM

S 5 on E face with 1 notch on W & 5 on E; from which: an Alder, 12" diam. bears S 32° E 32 lks. mkd "T 6 S R 10 W S 5 BT" Description of corner evidence found:

A Spruce, 16" diam, bears S 10° W 15 1ks mkd "T 6 S R 10 W S 6 BT" An Alder, 5" diam, bears N 17° E 26 1ks. mkd "T 6 S R 10 W CC S 5 & 6"

November 6, 1890"

I found a 3/4" pipe standing 20" above ground at the corner point. The SW BT is now a rotted stump. The SE BT is an uproot and the NE BT is gone.

Description of manument and accessories I established to perpetuate the original location of this corner

I set a 2 1/2" X 30" galvanized iron pipe with a flared bottom and a brasscap On the township line between the riveted to the top marked: T 5 S R 10 W Section Corner to the west and the

1/4 Corner to the east, S 6 S 5

T6S R 10 W 1973e RLS

from which:

30" Rotted Spruce stump bears S 10° W 13.9'

mkd "BT" visible (original BT)
10" Spruce bears S 31° W 15.4' mkd "T 6 S R 10 W S 6 CC BT"

10" Hemlock bears S 39° E 19.3' mkd "T 6 S R 10 W S 5 CC BT"

3/4" iron pipe bears N 01° 49' 22" E 3.95'

Witnessed: W.B. Jones E.W. Tatro

Slope: 40% Aspect: S 30° E

COUNTY SURVEYOR COUNTY OF TILLAMOSK PEGON . I hereby certify that the within instrument was filed in this office the start of the st REGISTERED

Set this 30th day of May 1973

BOOK

236

TIMBERLAND SERVICES, INC. P.O. Box 668 - Albany, Ore. 97321 Phone: 928-3539

PROFESSIONAL LAND SURVEYOR

OREGON JULY 17, 1970 KENNETH M. WIGHTMAN II 942

Form R6-7100-57 (9/66)