

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

This corner was originally set in 1890 under Contract No. 555, 40 chs North of $\frac{1}{12}$ 7. A post was set from which a:

16" hemlock S 58° E 7 lks.
6" hemlock S 79° W 9 lks.

DIAGRAM Y

E 1/4 Corner

Section 1 (Only)

Reference:

Plat dated July 1973 by Timberland Services, Inc. under my stamp.

Description of corner evidence found:

I found no evidence of either BT. However, I found an unrecorded 3/4" iron pipe and two BT's marked "T 6 S R 11 W 1/4 S 1 BT". This pipe set by LS 784 in 1969.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set a 2 1/2" X 30" galvanized iron pipe with a flared bottom and a brasscap riveted to the top marked: T 6 S R 11 W
1/4 S 1k
1973
RLS 942

By proportional measurement.

From which a:

6" Hemlock S 27° W 48.5 ft.
mkd "T 6 S R 11 W S 1 BT"
8" Hemlock S 62° W 29.4 ft.
mkd "T 6 S R 11 W S 1 BT"
3/4 " iron pipe S 74° E 1/54 ft.

These BT's are the above mentioned unrecorded BT's.

Witnessed: M. Jackson

Office of County Surveyor County of Tillamook
State of OREGON I hereby certify that the within instrument was filed in this office
for record on the 26th day of AUGUST, 1973, at 8:30 o'clock A.M., (signed)
[Signature] (DEPUTY)

Set this 26th day of July 1973.

BOOK 5 Edgar L Cook

253

Graduate Forest Engineer
Form R6-7100-57 (9/66)

TIMBERLAND SERVICES, INC.
P.O. Box 668 - Albany, Ore. 97321
Phone: 928-3529

