County Surveyor's Record. Tillamook County Oregon

8

Feet

from which

A Fir snag bears N40°E, 79 1ks This is an original BT-no scribing visible.

A Fir snag bears S36°E, 76 lks Original BT-no scribing visible.

A Fir snag bears S21°W, 88 lks Original BT--no scribing visible.

A Fir snag bears N45°W, 158 lks

Original BT-no scribing visible. A 20" Fir bears N50°E, 3.0 feet to face Face healed-scribing not visible.

A 42" Fir bears N54°W, 26.0 feet Face healed—scribing not visible.

Continuing on the line between T3 and 45, R9W

S89°05'57"E

Branch, 4 feet wide, course north 416 676 Branch, 4 feet wide, course north 1999 Descend 2450 Branch, 4 feet wide, course north 2557.87 Point for the reestablished position of the South 1/4 corner to Section 32. Made a diligent search for the stone Caudle set for this corner but could not find. At this point, I set a $2\frac{1}{2}$ " x 30" iron post with brass cap marked

> T3S R9W 32 1/4 1974 650

from which

A 26" Hemlock bears N33°E, 39.4 feet Scribed 1/4 S32 BT RS707. A 16" Alder bears N77°W, 19.6 feet Bark scribed 1/4 S32 BT 920.

An OSBF iron post with brass cap bears S64°08'11"W, 27.79 feet. Hemlock used above was a BT to this iron post. (See explanation of this situation in narrative).

Continuing on line between T3 and 4S, R9W

S89°05'57"E

3721 Branch, course N40°E 4793 Branch, 6 feet wide, course north 4857 Branch, 4 feet wide, course N15°W (fork of above) 4923.56 Closing corner to Sections 4 and 5 bears North 22.24 feet.

BOOK 5

See map B-661 HPLS650