

County Surveyor's Record, Tillamook County, Oregon

CHAINS

RESTORED CORNER FOR STATE OF OREGON--DEPARTMENT OF FORESTRY

Section corner common to Sections 24 and 25 (East side), T2S, R9W, W.M., Tillamook County, Oregon.

ORIGINAL

Stone (missing, in bed of slide and small spring branch) from which a:

9" Cedar bears S41 $\frac{1}{2}$ °W 71 lks.; now 33", scribes visible through opening, slope angle 44°.

20" Hemlock bears N3°W 116 lks.; now 51", scribes S19 visible on partially exposed face, slope angle 14°.

Note: Using slope distances both original BT's fit for distance and bearing.

RESTORATION by John Carlich (1961)

2" iron pipe (found torn out by logging operation)

Carlich did not mark any new BTS.

RESTORED

Var 21 $\frac{1}{2}$ °E

Set 1 $\frac{1}{2}$ " x 12" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T2S S24 S25 R9W T2S R8W S19 1975 RS707", 6 inches in concrete, in bedrock draw, course N30°W, with 2" pipe laying along side, and from which a:

51" Hemlock (orig) bears N3°W 72.6 ft. to new face; scribed BT RS 707.

33" Cedar (orig.) bears S42°W 33.2 ft. to new face; scribed BT.

73" Cedar stump bears S35 $\frac{1}{2}$ °W 35.1 ft. to face; scribed T2S R9W S25 BT.

2' base by 6' high rock out crop bears N77 $\frac{1}{4}$ °E 17.6 ft. to face; scribed XBO (3" letters).

Set 4" x 4" x 60" white painted Cedar post 17 ft. N79 $\frac{1}{2}$ °E of corner pipe. Oregon State Forestry Department metal location poster on 51" Hemlock.

Dated July 9, 1975

Restored by

Present and witnessed by Charles W. Cook
William E. Hollowell

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Harold J. Russell

OREGON
JULY 9, 1965
HAROLD J. RUSSELL
707