## County Surveyor's Record, Tillamook County, Oregon

CHAINS		the second of th
CHAINS		
er.		
-		
	A transport of the control of the co	
- :		
•		
: 41	RESTORED CORNER FOR STATE OF	OREGONDEPARTMENT OF FORESTRY
1 +4	l Avenue	
Witness P	oint common to Sections 4 and	d 33, T2 & 3N, R7W, W.M., Tillamook County
Oregon.		
	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
ORIGINAL		
and it		- m - c - 41 1 4 77 (
90" Fir Line tree bears S890 55'W 1.05 Chains from the 4 corner 4 and 33 (now an 82" stump cut below notches, bears N890 41' 23"W 68.33' from reestablished		
an 82" st	ump cut below notches, bears	N890 41. 23. 8 68.33. From reestabilished
4 corner	4 and 33).	
	The first of the second	
promobile		
RESTORED		
Set 5/8" x 16" Iron rod in the center of the stump, from which a:		
366 370		, and a second s
	5" Alder bears South 28.4 f	t. to face; Bark scribed LT S4 BT.
	12" Fir bears N624°W 89.5 ft	. to face; scribed LT S33BT RS707.
		$\mathcal{L}_{i}$
Dated Sep	tember 25, 1975.	
	0 02 1	
Restored	by Jozen Sleeke	under my direction.
	Loren Steele, Forest E	ngineer
		REGISTERED
		PROFESSIONAL
		LAND SURVEYOR
		Communication of the state of t
		Harved Stressell
		OREGON
		JULY 9. 1965
		HAROLD 4. RUSSELL
Present a	nd witnessed by P. Brunson	Company and the contract of th
	J. Martinez	fi Adjusti
100001		
	Like day	- 1988年・1987年 1987年 198
	Teach in	
	<b>- 李维的</b> 原	
		· · · · · · · · · · · · · · · · · · ·

358

ворк 5