History of original corner establishment:

1880 GLO set post 10" Alder bears South 59 lks 6" Alder bears North 26 lks DIAGRAM

T6S R9W S坛 Cor Sec. 1

Description of corner evidence found:

5/8" Iron Rod with white post 1 ft. East 30" White Fir bears N 20° 30' West 80.4 ft. 15" Fir bears S 11° East 115.5 ft.


Corner is located approximately 300 ft. North of house in marshy area

Description of monument and accessories I established to perpetuate the original location of this corner:

Set 2" galvanized pipe with 3" Brass Cap, 6" above ground stamped: Painted the faces of blazes and 6" band on existing witnesses Placed steel post with Attention sign, 2 ft. West of monument

T6S R9W
1₄ S 1
S 12
1975
PE 1956

See Map B. 701



Form R6-7100-57 (9/71)

☆ GPO---798-276

BUUK 5