ERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Fenton and Maloney survey in 1887 Corner is a post 5' long, 5" square, 24" in ground marked

T5S R8W GRIR on N

T6S on S

R8W S6 on E

R9W S1 on W faces with 6 notches SE and W edges from which:

a fir, 12" diam., bears S 58° E 56 1ks. marked T6S R8W S6 GRIR BT

a fir, 8" diam., bears S 57° W 43 lks. marked T6S R9W S1 BT a fir, 12" diam., bears N 39° E 16 lks. marked T5S R8W GRIR BT

DIAGRAM

NE Cor S1 NW Cor S6.

only

T6S, R9W and T6S, R8W, WM

Description of corner evidence found:

Found 1" pipe 24" above ground
Found 36^M fir stump bearing N 31^O W 10.5' with scribe marks GRI
Found 32" fir stump bearing S 58^O E 36.9' with scribe marks 6 GRIR Found 9" alder bearing S 340 E (side center) 18.8' with bark scribe T6S R8W S6 BT Found 8" alder bearing S 40° W (side center) 13' with bark scribe T6S R9W S1 BT Found aluminum angle post with attention sign 3' south of pipe


Corner is in young stand of alder in head of shallow draw running down S $40^{\rm o}$ W

Description of monument and accessories I established to perpetuate the original location of this corner:

Set 3" brass cap and 2" iron pipe 6" above ground, stamped:

Painted 6" red band on 9" alder and 8" alder and placed attention sign on back of each Painted faces of both BT stumps

Placed pipe on N side of mon. in hole



See map 3-701



Office of Sunty Sugueyor	County of
State of Second I hereby certify to	hat the within linstrument was filed in this office
for regard on the 17th day of NOVENBER by	(DEPUTY)

Form R6-7100-57 (9/71)

☆ GPO---798-276

BOOK 5 .