

## History of original corner establishment:

Corner established by Charles E. Branson, Deputy Surveyor, under Contract No. 687, dated June 8, 1898. Original survey states: Intersect W. bdy. of TP 87 lks. N. of cor. of Sec. 12 & 13, which is a post, mkd. and witnessed as described by the Surveyor General. At point of intersection, I set:

An alder post, 5 ft. long, 4 ins. sq., 24 ins. in the ground, T4S S7 on NE., and CC on E. and R9W S18 on SE., for closing cor. to Secs. 7 & 18 from which: A dead fir,

DIAGRAM

TAS TAS

RIOW S7 CC
S12 S18

R9W

50 ins. diam., brs. N56°30'E, 200 lks. dist. Mkd: T4S R9W S7 BT (this tree is the original BT of Sec. 7). I did not destroy marks on the original, except those referring to Sec. 7.

M. Whitmore, Deputy Surveyor, Tillamook Co., perpetuated and recorded this corner on April 17, 1953.

## Description of corner evidence found:

1/2" pipe 2 ft. above ground by a 4"X4" wood post 2-1/2 ft. above ground. Set by M. Whitmore, 4/17/53.

16" alder, N40°E, 38.4 ft., Mkd: T4S R9W S7 CC B.T. (set by M. Whitmore, 4/17/1953).

20" alder, S59°E, 40.0 ft. Mkd: T4S R9W S18 CC BT (M. Whitmore, 4/17/1953).

50" fir snag, N56°30'E, 129.1 ft., Mkd: T4S R9W S7 BT (original B.T.)

Description of monument and accessories I established to perpetuate the original location of this corner:

Set a 30" by 2-1/2" diam. iron pipe with 2-1/2" diam. brass cap, flared on bottom.

Mkd:

T45 T45

RIOW | S7 CC

S12 | S18

R9W

1976

RLS 1050

1/2" pipe buried along side of cap.
Painted 6" red band around B.T.'s.
Attached new B.T. signs.
Attention signs on back side of B.T.'s
6' metal fence post set 3' east of cap with attention sign attached.

Witnessed: F. Wratni

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON AUGUST 22, 1975 L. W. HUNNEMULLER 1050

Office of COUNTY OFFICIAL)

County of County o

Form R6-7100-57 (9/71)

☆ GPO---798-276