CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

None

DIAGRAM

T 4 S R 8 W

W-E

1/64

S2

Description of corner evidence found:

None

Description of monument and accessories I established to perpetuate the original location of this corner:

At proportionate measurement I set a 2 1/2" X 30" galvanized iron pipe with a flared bottom and a brasscap riveted to the top marked:

Set two steel fence posts with Property Boundary signs and Land Survey Monument signs. All bearing trees have brass washers and attention signs, bearing tree tags and red painted bands.

Witness: Jay McDonald

D. Mike Jackson Enigneering Technician

Office of CONNETY SURVEY County of TIMEDIACOLIA KENNETH M. WIGHTMAN II


for record on the Comment day of Association by (COUNTY OFFICIAL)

CONTRACTOR OF

Form R6-7100-57 (9/71)

Booke 6

19 19



TIMBERLAND SERVICES, INC. 1010 Airport Road P. O. Sox **658** Albany, Oregon 973²⁰ Telephone (503) 926-94²⁰

LAND SURVEYING - ENGINEERING LAND USE PLANNING - ROADS FORESTRY CONSULTING REGISTERED
PROFESSION*:
LAND SURVE: 3

REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON

OREGON
JULY 30, 1976
EDGAR R. COOK

- 13