CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

None

DIAGRAM

T 4 S R 8 W

NW 1/16

S2

E

Description of corner evidence found:

None

Description of monument and accessories I established to perpetuate the original location of this corner:

At proportionate measurement I set a 2 1/2" X 30" galvanized iron pipe with a flared bottom and a brasscap riveted to the top marked:

T 4 S R 8 W

NW 1/16

S2

1977

RLS 1073

From Which,

19" D. Fir N 02° E, 21.1 feet

mkd "NW 1/16 S 2" "B.T."

12" Alder S 87° E, 3.3 feet

Bark Scribed "NW 1/16 S 2" "B.T."

I set two 6' steel fence posts with property boundary signs and land survey monument signs. All bearing trees have brass washers, attention signs, bearing tree tags, red painted bands.

Witness: Jay McDonald

D. Mike Jackson Engineering Technician

Office of SOUNTY SUCKEYOR County of THAT MAKEN HENNETH M. WIGHTMAN IX

State of No. 1 hereby certify that the within instrument was filed in this office for record on the condition and the condition of the conditi antin , Going Suguesco.

(COUNTY OFFICIAL)

(DEPUTY)

Form R6-7100-57 (9/71)

Books 6 1482



TIMBERLAND SERVICES, INC. 1010 Argert Boas - P. O. Box 668 Albany, Oregon - \$7321 Felephone - (\$03) 925-\$404

LAND SURVEYING - ENGINEERING LAND USE PLANNING - ROADS FORESTRY CONSULTING

REGISTERED PROFESSIONAL AND SURVEYOR

REGISTERED PROFESSIONAL

EGON EDGAR R. COOK 1073