CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

None

DIAGRAMT 4 S R 8 W
C-S-N-N
1/256
S2

✓

Description of corner evidence found:

None

Description of monument and accessories | established to perpetuate the original location of this corner:

At proportionate measurement I set a 2 1/2" X 30" galvanized iron pipe with a flared bottom and a brasscap riveted to the top marked:

T 4 S R 8 W From Which,

S2 2" Alder S 50° E, 50.3 feet
mkd "C S N N 1/256" "B.T." Bark Scribed

1/256 1977

RLS 1073

I set a 6' steel fence post with Boundary signs and Land Survey signs. All bearing trees have brass washers, attention signs, bearing tree tags, and red painted bands.

Witness: Marvin Kirk

See hop B-764

Diffice Jackson
Engineering Technician

Office of SUNTY SURVEYOR County of State of SETTION I hereby certify that the within instrument was filed in this office for record on the & day of AUGUST 19.

(COUNTY OFFICIAL) by CAUNTY SURVEYOR-

Form R6-7100-57 (9/71)

Book Pg 31

TIMBERLAND SERVICES, INC. 1010 Airport Boad P. O. Box 868 Albany, Oregon 97321 Telephone (503) 928-9404

LAND SURVEYING - ENGINEER**ING** LAND USE PLANNING - ROADS FORESTRY CONSULTING REGISTERED
PROFESSION**
LAND SURVE

KENNETH M. WIGHTMAN III 942

REGISTERED PROFESSIONAL

OREGON
JULY 30, 1976
EDGAR R. COOK