CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

None

DIAGRAM

T 4 S R 8 W
C-N-NW-SE
1/256
S2

N

Description of corner evidence found:

None

SEE RESET OF THIS
FOR ORNER 3/8/ Dumen Cas.

Description of monument and accessories I established to perpetuate the original location of this corner:

At proportionate measurement I set a $2\ 1/2$ " X 30" galvanized iron pipe with a flared bottom and a brasscap riveted to the top marked.

T 4 S R 8 W From Which,

S2 20" Alder S 21° E, 30.0 feet mkd "CNNWSE 1/256" BT"

20" Alder N 85° W. 47.5 feet mkd "C N NW SE 1/256" "B.T."

Both Bark Scribed

RLS 1073

Set fence post with property boundary signs and land survey monument signs. All bearing trees have brass washers, attention signs, bearing tree tags, red painted bands.

Witness: Marvin Kirk

Lee map 3-76 m

Engineering Technician

Office of SANT SURVEYOR County of State of SANT AND SURVEYOR

(COUNTY OFFICIAL)

REGISTERED PROFESSIONAL LAND SURVEYOR

REGISTERED PROFESSIONAL LAND SURVEYOR

REGISTERED PROFESSIONAL LAND SURVEYOR

REGISTERED PROFESSIONAL LAND SURVEYOR

Form R6-7100-57 (9/71)

Book 6 Pg 31

THMBERL 1010 Art All Tales LANO SU

TIMBERLAND SERVICES, INC. 1010 Arport Read P. O. Box 666 Albany Oregon 97321 Talephone (803) 926-9404

LAND SURVEYING - ENGINEERING LAND USE PLANNING - ROADS FORESTRY CONSULTING LAND SURVEYOR
LAND LOOL

EDGAR R. GOOK