CERTIFIED RECORD OF LAND CORNER MONUMENTATION


History of original corner establishment:

None

DIAGRAM T 4 S R 8 W NW SE 1/64 S 2

Description of corner evidence found:

None



Description of monument and accessories I established to perpetuate the original location of this corner:

At proportionate measurement I set a 2 1/2" X 30" galvanized iron pipe with a flared bottom and a brasscap riveted to the top marked:

T4S R8W

From Which,

S2

NW - SE

1/64

1977

RLS 1073

20" Alder S 76° E, 27.8 feet mkd "NW-SE 1/64 S 2" "B.T." Bark Scribed 24" D. Fîr N 41° E, 41.5 feet mkd "1/64 S 2 B.T."

I set a 6' steel fence post with boundary and survey monument signs. All bearing trees have brass washers, attention signs, bearing tree tags and red painted bands.

Witness: Ed Tatro

Lee May 3-764

D. / Mike Jackson Engineering Technician

Office of COUNTY STATES County of The SACOR STATES

OREGON

REGISTERED PROFESSIONAL LAND SURVEYOR

for record on the & day of Assass. , 19.1.

State of . O. P. T. CON. I hereby certify that the within instrument was filed in this office KENNETH M. WIGHTMAN II 9 4 2

Candid by COUNTY SURVEYOR (COUNTY OFFICIAL)

Form R6-7100-57 (9/71)

Books

pg 32



TIMBERLAND SERVICES, INC. 1010 Airport Road P. O. Box 668 Albany, Oregon 97521 Telephone (500) 975-9404

LAND SURVEYING - ENGINHERING LAND USE PLANNING - ROADS FORESTRY CONSULTING

PROFESSION"

REGISTERED

OREGON EDGAR R. COOK 1073