CrownZellerbach	LAND	CORNER	RECORD	jc s.w. PORTLAND,	FIRST AVE. ORE. 97201
T 3S , R 10W , W Segregated Surveys:		Tillamook	County Corner Code No		
Name: CW 1/16 Sec.7,	T3S., R10W.	W., W.M. Corner No.:			
1. History of Corner Estal In a survey of Sec.7, set a 4"x4" spruce lintwo bearing trees: a N8°30'E 47.5 ft. In Zellerbach Corporation replaced it with a 1" set next to the pipe	T.3S., R.1 mb for the 72" dia. s 1956 an unr n engineers galvanized	OW., W.M. comp southwest corr pruce bears N8 ecorded survey . They found iron pipe wit	pleted in Februarer of the SE4NV 38°E 42.5 ft., and of section 7 version 4 in square he 2" Babbit cap	W <sub>4</sub> , from which and a 48" heml was completed re spruce limb o. The spruce	n he marked lock bears by Crown o, and
2. Description of Evidence	e Found:				
poster standing next I also found both bear badly decayed stump w 47.5 ft.) is now a bad	ring trees. ith no evid	The 72" dia.	spruce (N88°E ing. The 48" di	42.5 ft.) is ia. hemlock (N	now a 18°30'E
				1944	
3. Describe Monument, Acgram corner and indication					
I left the 4" square in good condition. I edge of a logging road alder in a creek bottoyellow metal location	set two ne d bears N82 om bears S5	w bearing tree °W 29.4 ft. to 5°30'E 23.5 ft	es; a 7" dia. Do o face marked "C c, bark scribed	ouglas fir on CW 1/16 BT."	the west A 10" dia.
			en e		
eringen Jahren Gartin					
iide Tangan an an an An Angan		(			
Oregon Coordinate Syste	em:	Zone, Y		, <b>x</b>	
Pin Pointed on Photo No.			***************************************	<u> </u>	
			Located at	WW.5.4.5.4	
This corner record correction in co	mpliance wi	ts work perforn th the provision	ns of ORS 209.25	REGISTEI PROFESSI PLAND SUR	
Taws of 1930. Date	sen) 4-24	P150	701	Robert J. O	
Signature		59	ertificate No.	ODECO	The state of the s
6				ROBERT	SEN

Воок 6