Oswald West Survey  $NE_4^1$  Section 1, T3N, R11W, W.M. Sections 5 & 6, T3N, R1OW, W.M. Tillamook County December 22, 1981 Page 6

24" hemlock bears N81°E, 28½ links, marked "½SBT" (now a 40" hemlock). 27" hemlock bears N72½°W, 64 links, marked "½SBT" (now a rotted stump).

#### STATE PARKS CREW FOUND:

A 4" square post. 40" hemlock N80½°E, 20.2' to center, "¼" visible in blaze, original BT. 28" rotten stump N65°W, 43.0' to center, original BT.

#### STATE PARKS CREW SET:

5/8"x30" iron rod with aluminum cap marked "OSHD STATE PARKS DIV." Galvanized steel post with plain white paddle 2.0' south of iron rod. 13" hemlock 21.5' to center \$50°W, scribed " $\frac{1}{4}$ \$6BT R\$691" and attached yellow Parks corner tag.

## WITNESSED BY:

- R. Hemmer
- S. Doak M. Swan

# 4 CORNER BETWEEN SECTIONS 1 AND 6

ORIGINAL: 1873

Marked a 8" hemlock for 4 section corner.

#### 1892:

On steep mountain side, finding no corner after diligent search, set post 3' long, 3" square, 24" in ground, for  $\frac{1}{4}$  section corner, marked " $\frac{1}{4}$ S" on west face from which a:

36" spruce bears N4°W, 57 links, marked "%SBT." No other trees within limits.

Also make a mound of rocks  $4\frac{1}{2}$  at base,  $2\frac{1}{2}$  high around the post.

STATE PARKS CREW FOUND:

Nothing.

## STATE PARKS CREW SET:

5/8"x30" iron rod with aluminum cap marked "OSHD STATE PARKS DIV." Galvanized steel post with plain white paddle 2.0' west of iron rod. 18" hemlock S52°E, 35.1' to center, scribed "T3N R10W  $^{1}\!_{4}\!S6BT$  RS691" and attached yellow Parks corner tag. 77" spruce \$70°W, 41.0' to center, blazed but not scribed as wood too rotten to scribe.

## WITNESSED BY:

- R. Hemmer
- L. Boge
- S. Doak
- M. Swan

# WC ON TOWNSHIP LINE 1.75 CHS WEST OF SECTION CORNER

ORIGINAL: 1892

30" hemlock (found to be a spruce) marked: "T4N S33 WC" on NE, "R10W S4" on SE, "T3N S5" on  $\dot{SW}$  and "S32  $\dot{WC}$ " on  $\dot{NW}$  faces with 4 notches on the east and 2 on the west edges from which a:

220