## REWITNESSED CORNER FOR STATE OF OREGON--DEPARTMENT OF FORESTRY

One-Quarter corner common to Sections 2 and 3, T3N, R6W, W.M., Tillamook County, Oregon.

ORIGINAL

Post (missing). from which a:

24" fir bears N33°E 31 lks.; now a rotten root crown. 60" fir bears N72½°W 23 lks.; now a 60" fir snag 12' high.

RESTORATION by OSHD, 1941.

Found 60" fir bearing tree.
Found a rotten fir stump for other bearing tree from which ▶:

Set concrete monument with  $2\frac{1}{2}$ " brass cap (in place). Set 4" x 4" white guard post (in place). 30" fir bears N85°E 60.2 ft.; now a 36" fir snag 10' high with scribes visible.

REWITNESSED

VAR. 21½°E

Above mentioned concrete monument, from which a:

9" fir bears S66½°E 5.1 ft. to face; scribed 1/4 S2 BT. 12" fir bears S30½°W 9.6 ft. to face; scribed 1/4 S3 BT.

Oregon State Forestry Department metal location poster on 12" fir BT S30½°W 9.6'.

Dated April 20, 1983.

Restored by

under my direction.

REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON
JULY 14, 1978
LOREN R. STEELE
1662

Present and witnessed by S. Ellis.

0. Hendrick.