## REWITNESSED CORNER FOR STATE OF OREGON--DEPARTMENT OF FORESTRY

One-Quarter corner common to Sections 1 and 36, T3&4N, R6W, W.M., Tillamook and Clatsop Counties, Oregon.

ORIGINAL

Post (missing). from which a:

20" fir bears N60°E 20 lks.; now a 20" fir uprooted stump with scribes BT visible. 24" fir bears South 8 lks.; now a 26" fir stump S28½E 5.28' with scribes BT visible.

RESTORATION by OSHD, 1941.

Found 2 bearing trees marked  $\frac{1}{4}S$  BT and a  $1\frac{1}{2}$ " iron pin. Replaced the pin with a 2" x 48" galvanized iron pipe with a brass cap (in place). Set a 4" x 4" white guard post (in place). Did not scribe BT's.

REWITNESSED

VAR. 21½°E

Above mentioned 2" x 48" pipe, from which a:

- 11" fir bears N48½°E 9.1 ft. to face; scribed 1/4 S36 BT. 12" fir bears S46½°E 16.2 ft. to face; scribed 1/4 S1 BT. 2' creek bears South 59.0', crs. N85°E from N80°W. 2' creek bears East 130.0', crs. North from S38°W.

Oregon State Forestry Department metal location poster on 11" fir BT N48½°E 9.1'.

Dated April 29, 1983.

Restored by

under my direction.

REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON JULY 14, 1978 LOREN R. STEELE 1662

Present and witnessed by O. Hendrick.