RESTORED CORNER FOR STATE OF OREGON--DEPARTMENT OF FORESTRY

Section corner common to Sections 1, 2, 35, and 36, T3&4N, R6W, W.M., Tillamook and Clatsop Counties, Oregon.

ORIGINAL

5" vinemaple for corner (missing) from which a:

24" fir bears N80°E 22 lks.; now a 28" stump with axe work visible, East 19.9'.

12" hemlock bears S45°E 23 lks.; now a 12" badly rotted uproot with axe work visible.

24" fir bears S2°W 10 lks.; now a 24" badly rotted uproot.

36" fir bears N30°W 12 lks.; now a 36" stump with axe work visible.

RESTORED

VAR. 21½°E

Set 2" x 36" aluminum pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T4NR6WT3NS1S2S35S361983RS1662", 35 inches in ground, and from which a:

14" fir bears N483/4°E 10.8 ft. to face; scribed T4NR6W S36 BT.

16" fir bears S66½°E 20.7 ft. to face; scribed T3NR6W S1 BT.

18" fir bears \$73°W 9.3 ft. to face; scribed T3NR6W \$2 BT.

13" fir bears N64°W 27.9 ft. to face; scribed T4NR6W S35 BT.

OSHD 2" x 48" galvanized iron pipe with brass cap bears N31°58'52"E 2.72'.

Set 4" x 4" x 60" white painted Cedar post NE 1.0 ft. from corner pipe.

Oregon State Forestry Department metal location poster on 18" fir BT S73°W 9.3'.

Dated May 2, 1983.

Restored by_

under my direction.

REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON
JULY 14, 1978
LOREN R. STEELE

Present and witnessed by S. Ellis.

0. Hendrick.