REWITNESSED CORNER FOR STATE OF OREGON--DEPARTMENT OF FORESTRY

One-Quarter corner common to Sections 2 and 35, T3&4N, R6W, W.M., Tillamook and Clatsop Counties, Oregon.

Post (missing). from which a:

10" cedar bears N32°W 17 lks.; now a 10" cedar uproot with scribes visible. 26" hemlock bears S54°W 21 lks.; now a 30" hemlock stump, face and scribes rotted away.

RESTORATION by OSHD, 1941.

Found 2 dead BT's.

Set a 2" x 48" galvanized iron pipe with brass cap (in place).

Set 4" x 4" white guard post (in place).

Did not scribe BT's.

REWITNESSED

VAR. 21½°E

Above mentioned 2" \times 48" pipe, from which a:

14" fir bears N46°E 5.7 ft. to face; scribed 1/4 S35 BT. 11" fir bears S233/4°E 30.8 ft. to face; scribed 1/4 S2 BT.

Oregon State Forestry Department metal location poster on 14" fir BT N46°E 5.7'.

Dated April 29, 1983.

Restored by

__under my direction.

REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON

JULY 14, 1978

LOREN R. STEELE

1662

Present and witnessed by 0. Hendrick.