RESTORED CORNER FOR STATE OF OREGON - DEPARTMENT OF FORESTRY Standard section corner common to Sections 31, and 36, T1N, R7&8W, W.M., Tillamook County, Oregon.

ORIGINAL By Samuel D. Snowden, September 14, 1856.

Post; missing.

9" Hemlock bears N68°W 17 lks.; portions of root system in

8" O. Hickery bears SO8°E 12 lks.; missing. 6" Vinemaple bears S31°W 44 lks.; missing. 3" O. Hickery bears N40°E 29 lks.; missing.

RESTORATION by Henry Meldrum, August 9, 1884.

Post; missing.

RESTORATION by A.V. Benedict, RE1960, February 28, 1942 (Book 1, page 15 and 173, Tillamook County Records).

3/4" iron rod, 4 ft. long, 3 ft. in ground, in mound of rock; in place. Squared Cedar stake; missing.

60" Dead Cedar bears S03°W 75.2 ft.; now a 60" snag with scribes S31 36 1 & 6 R1 8W BT visible. Also cruiser marks AL and K above face.

20" Dead Cedar bears S48°E 55.6 ft.; now a 20" windfall with portions of scribes visible.

Var 21 1/2⁰E RESTORED Placed a 1"x30" galvanized iron pipe with yellow plastic cap marked "LS1998", 24" in ground over 3/4" iron rod and from which a:

21" Fir bears N15°E 28.1 ft. to face; scribed T1NR7WS31SCBT. 23" Fir bears N53°W 49.6 ft. to face; scribed T1NR8WS36SCBT. Ridge top bears East 20.1 ft.; S22°E by Same. Same ridge top bears North 41.8 ft.; S22°E by Same.

Metal location poster on new BTs.

Dated May 29, 1987.

Restored by



Present and witnessed by David B. Buchholz Clifford R. Foster